PATENT DOCKET NO.: 13372/24

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANT: Nobuaki KIYA Confirmation No. 6906

SERIAL NO. : 10/590,235

FILED: August 22, 2006

FOR : METHOD OF DETECTING AND RESPONDING TO A

COOLING SYSTEM FAILURE IN A POWER SUPPLY DEVICE

(as amended)

PATENT NO.: : 7,771,864 B2 Issued 10 August 2010

#### CERTIFICATE OF CORRECTION BRANCH

COMMISSIONER FOR PATENTS P. O. Box 1450 Alexandria, VA 22313-1450

# REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R §1.323

SIR:

It is respectfully requested that the enclosed certificate of correction be issued for the above Patent under authority of 35 USC  $\S$  355.

The changes represent correction of minor errors which were not previously discovered.

The fee under 37 C.F.R. 1.20(a) in the amount of \$100.00 is being paid by credit card. If a petition is required to correct these errors, please consider this such a petition and charge the fee in the amount of \$130.00 to Deposit Account No. 11-0600.

Respectfully submitted,

Dated: 23 December 2010 /Shawn W. O'Dowd/

Shawn W. O'Dowd (Reg. No. 34,687)

KENYON & KENYON LLP 1500 K Street, N.W., Suite 700 Washington, DC 20005

Tel: (202) 220-4200 Fax: (202) 220-4201

### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

7,771,864 B2

Page 1 of 1

**DATED** 

10 August 2010

**FILED** 

22 August 2006

**INVENTOR(S)** 

Nobuaki KIYA, et al

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column	<u>Line</u>	
16	55	Before "according" delete "a".
17	16	After "cooling system" delete "is set".

MAILING ADDRESS OF SENDER:

Shawn W. O'Dowd KENYON & KENYON LLP 1500 K Street, N.W., Suite 700 Washington, DC 20005 Patent No.: 7,771,864 B2